## Agenda Item #8 - Construction Amendments and Changes Log (Transit Center)

8/	17/2018									•
Trade Package	CCO/CR No.	Total Value	Date submitted to CRC	Date No Exceptions Taken by CRC	Amount No Exceptions Taken by CRC	CCO Final Approved Amount	CCO Category	Contingency Source	Fund Source	CCO Issue
7.2	COR 310937	\$800,000	8/31/2017	8/31/2017	\$800,000		Owner Requested	ner Requested TJPA	TIFIA	Pour backs for curbs, other curb issues related to W2 system, General Closeout Items
10.2	COR 310461	\$325,000	5/18/2018		\$325,000		Owner Requested	TJPA	CFD	CM/GC Trailer Relocation Due to TJPA Sale of Lot N
10.4	COR 310485	\$7,400,000	2/16/2018		\$7,400,000		Owner Requested	TJPA	CFD	ASI 131 "No Fly Zone"
		41,100,000	_,,	2, 20, 2020	41,100,000				<u> </u>	
		<u> </u>	<u> </u>	L			Erro	ors & Omissions		
10.2	COR 311901	\$1,000,000	8/24/2018				Errors & Omissions	TJPA	CFD	Revised Supports for Piping in Service Corridors
10.4	COR	\$300,000	8/24/2018				Errors & Omissions	TJPA	CFD	RFI T-6974.1 Modified LE-281 Fixture and Power Feed Location
10.4	COR	\$300,000	8/24/2018				Errors & Omissions	TJPA	CFD	RFI-T 6854.1 Installation of Dedicated Emergency Circuit for Elevator Monitoring System
10.4	COR 313473	\$2,000,000	8/24/2018		4		Errors & Omissions	TJPA	CFD	RFI T-7267 Power to Signage Pylons
10.4	COR 312021	**\$800,000	2/16/2018		\$760,000		Errors & Omissions	TJPA	CFD	RFI T-5960 Added Door Power
7.2	COR	\$3,000,000	11/10/2017	11/17/2017	\$3,000,000		Errors & Omissions	TJPA	CFD	General Closeout Items
7.2 10.2	COR COR	\$310,000 \$450,000	8/31/2017 11/10/2017	8/31/2017	\$310,000 \$450,000		Errors & Omissions Errors & Omissions	TJPA TJPA	CFD CFD	Escalator Issues - Added Mid-Span Support.
10.2	COR 312719	\$350,000	2/16/2018	11/17/2017 2/16/2018	\$350,000		Errors & Omissions	TJPA	CFD	RFI T-6805 Wrapping Fuel Oil Piping in Lieu of 2 Hour Enclosure  IDF Room Build-out
10.4	COR 312719	\$2,300,000	11/7/2016		\$2,300,000		Errors & Omissions	TJPA/CMGC	CFD	Hardened Conduit RFI T-3669
13.1	COR 311163	\$100,000	8/31/2017	8/31/2017	\$100,000		Errors & Omissions	TJPA	CFD	Change to Glass Type for Bus Glass Wall
16.0	COR	\$1,000,000	2/16/2018		2/16/2018		Errors & Omissions	TJPA/CMGC	CFD	Skanska General Scope Closeout Items
18.1	COR 310480	\$700,000	11/10/2017	11/17/2017	\$700,000		Errors & Omissions	TJPA	TIFIA	Revised sizes for Link Beams per ASI 150, General Design Issues
18.1	COR	\$1,000,000	11/10/2017	11/17/2017	\$1,000,000		Errors & Omissions	TJPA	CFD	General Closeout Items
10.1	0011	<b>\$1,000,000</b>	11/10/2017	11/11/2017	\$1,000,000		Errors & Ornissions	13171	CID	Scholar closecut richis
							Scho	edule Mitigation		
7.2	COR 311070.1	\$450,000	2/16/2018	2/16/2018	\$450,000		Schedule Mitigation	CMGC	CFD	Dry Finish Acceleration Part 2
7.6	COR	\$1,000,000	2/16/2018		\$1,000,000		Schedule Mitigation	CMGC	CFD	Trade Package 12.1 to 07.6 Scope Transfer Reconciliation (Ref CCO 503, 1112, and Zones 1-3)
8.6R	COR 312232	\$800,000	2/16/2018		\$800,000		Schedule Mitigation	CMGC	CFD	Storage of W-14 Ceiling Panels
10.4	COR 311616.2	\$280,000	2/16/2018		\$280,000		Schedule Mitigation	CMGC	CFD	Single Line - Acceleration
10.4	COR 311967	\$380,000	2/16/2018		\$380,000		Schedule Mitigation	CMGC	CFD	Electrical Zone 4 Acceleration
10.4	COR	\$600,000	2/16/2018		\$600,000		Schedule Mitigation	CMGC	CFD	Supplemental Man-power - Rosendin
10.4	COR 311736	\$310,000	2/16/2018		\$310,000		Schedule Mitigation	CMGC	CFD	SFPUC Vault Acceleration
16.0	COR 311825	\$600,000	11/10/2017	11/17/2017	\$600,000		Schedule Mitigation	TJPA	CFD	Skanska Inefficiency Costs
								Coordination		
7.2/7.6	COR 311374	\$375,000	8/31/2017	8/31/2017	\$375,000		Coordination	CMGC	CFD	Curb Extension at Elevator Fronts for All Elevator Shafts
10.2	COR 311901	\$700,000	2/16/2018	2/16/2018	\$700,000		Coordination	CMGC	CFD	RFI T-6025 - Revised Supports to Account for Phase 2 Mechanical Duct
							Co	de Compliance		
10.4	COR 311826	\$650,000	2/16/2018	2/16/2018	\$650,000		Code Compliance	TJPA	CFD	Fire Management System Changes
		41= 111 000	0/04/0040	I	I		Close	etout/Settlement	0=0 / 0:: =: .	
Various	COR	\$17,414,000	8/24/2018				Con	no Dunguyamant	CFD/ City Financing	General Closeout Items for all Trades and Resolution with Resolveable Claims
10.2	COD 211927.1	\$700,000	•	ı			500	pe Procurement		
10.2 10.4	COR 311837.1		0/24/2010				Coope Drocurement	TIDA	CED	DC 9.E added Supports for Cas Motor
7.2			8/24/2018				Scope Procurement	TJPA	CFD CFD	PG&E added Supports for Gas Meter
	COR 312021.2	\$450,000	8/24/2018		\$650,000		Scope Procurement	TJPA	CFD	120V Power to Crown Corr Doors
	COR 310599	\$450,000 \$650,000	8/24/2018 11/10/2017	11/17/2017	\$650,000 \$370,000		Scope Procurement Scope Procurement	TJPA CMGC	CFD CFD	120V Power to Crown Corr Doors  Deck Steel Plates at Tall Curbs
7.2	COR 310599 COR 311646	\$450,000 \$650,000 \$370,000	8/24/2018 11/10/2017 11/10/2017	11/17/2017 11/17/2017	\$370,000		Scope Procurement Scope Procurement Scope Procurement	TJPA CMGC CMGC	CFD CFD CFD	120V Power to Crown Corr Doors  Deck Steel Plates at Tall Curbs  Roof Built Up Slab
7.2 10.4	COR 310599 COR 311646 COR 311155-1	\$450,000 \$650,000 \$370,000 \$1,200,000	8/24/2018 11/10/2017 11/10/2017 4/5/2018	11/17/2017 11/17/2017 3/21/2018	\$370,000 \$1,200,000		Scope Procurement Scope Procurement Scope Procurement Scope Procurement	TJPA CMGC CMGC TJPA	CFD CFD CFD	120V Power to Crown Corr Doors  Deck Steel Plates at Tall Curbs  Roof Built Up Slab  ASI 143 - Incorporation of Phase 1.5 Converge Network Package
7.2 10.4 10.4	COR 310599 COR 311646 COR 311155-1 COR 311397	\$450,000 \$650,000 \$370,000 \$1,200,000 \$2,100,000	8/24/2018 11/10/2017 11/10/2017 4/5/2018 2/16/2018	11/17/2017 11/17/2017 3/21/2018 2/16/2018	\$370,000 \$1,200,000 \$2,100,000		Scope Procurement Scope Procurement Scope Procurement Scope Procurement Scope Procurement	TJPA CMGC CMGC TJPA CMGC	CFD CFD CFD CFD CFD	120V Power to Crown Corr Doors  Deck Steel Plates at Tall Curbs  Roof Built Up Slab  ASI 143 - Incorporation of Phase 1.5 Converge Network Package  A1 Light Fixtures
7.2 10.4	COR 310599  COR 311646  COR 311155-1  COR 311397  CR T-517	\$450,000 \$650,000 \$370,000 \$1,200,000	8/24/2018 11/10/2017 11/10/2017 4/5/2018	11/17/2017 11/17/2017 3/21/2018 2/16/2018 11/17/2017	\$370,000 \$1,200,000 \$2,100,000 \$2,500,000		Scope Procurement	TJPA CMGC CMGC TJPA CMGC TJPA CMGC TJPA	CFD CFD CFD	120V Power to Crown Corr Doors  Deck Steel Plates at Tall Curbs  Roof Built Up Slab  ASI 143 - Incorporation of Phase 1.5 Converge Network Package
7.2 10.4 10.4 10.4	COR 310599 COR 311646 COR 311155-1 COR 311397	\$450,000 \$650,000 \$370,000 \$1,200,000 \$2,100,000 \$2,500,000	8/24/2018 11/10/2017 11/10/2017 4/5/2018 2/16/2018 11/10/2017	11/17/2017 11/17/2017 3/21/2018 2/16/2018	\$370,000 \$1,200,000 \$2,100,000		Scope Procurement Scope Procurement Scope Procurement Scope Procurement Scope Procurement	TJPA CMGC CMGC TJPA CMGC	CFD CFD CFD CFD CFD CFD	120V Power to Crown Corr Doors  Deck Steel Plates at Tall Curbs  Roof Built Up Slab  ASI 143 - Incorporation of Phase 1.5 Converge Network Package  A1 Light Fixtures  TG10.4 Revised ERRCS Scope From ASI 134
7.2 10.4 10.4 10.4 10.4	COR 310599 COR 311646 COR 311155-1 COR 311397 CR T-517 COR 311034	\$450,000 \$650,000 \$370,000 \$1,200,000 \$2,100,000 \$2,500,000 \$1,100,000	8/24/2018 11/10/2017 11/10/2017 4/5/2018 2/16/2018 11/10/2017 8/31/2017	11/17/2017 11/17/2017 3/21/2018 2/16/2018 11/17/2017 11/17/2017 8/31/2017	\$370,000 \$1,200,000 \$2,100,000 \$2,500,000 \$1,100,000		Scope Procurement	TJPA CMGC CMGC TJPA CMGC TJPA TJPA/Reimbursable	CFD CFD CFD CFD CFD CFD CFD CFD CFD SFPUC	120V Power to Crown Corr Doors  Deck Steel Plates at Tall Curbs  Roof Built Up Slab  ASI 143 - Incorporation of Phase 1.5 Converge Network Package  A1 Light Fixtures  TG10.4 Revised ERRCS Scope From ASI 134  SFPUC Switchgear and Cabling Additional Work.
7.2 10.4 10.4 10.4 10.4 14.1B	COR 310599 COR 311646 COR 311155-1 COR 311397 CR T-517 COR 311034 COR 311970	\$450,000 \$650,000 \$370,000 \$1,200,000 \$2,100,000 \$2,500,000 \$1,100,000 \$450,000	8/24/2018 11/10/2017 11/10/2017 4/5/2018 2/16/2018 11/10/2017 8/31/2017 8/31/2017	11/17/2017 11/17/2017 3/21/2018 2/16/2018 11/17/2017 11/17/2017 8/31/2017	\$370,000 \$1,200,000 \$2,100,000 \$2,500,000 \$1,100,000 \$280,000		Scope Procurement	TJPA CMGC CMGC TJPA CMGC TJPA TJPA TJPA/Reimbursable TJPA	CFD	120V Power to Crown Corr Doors  Deck Steel Plates at Tall Curbs  Roof Built Up Slab  ASI 143 - Incorporation of Phase 1.5 Converge Network Package  A1 Light Fixtures  TG10.4 Revised ERRCS Scope From ASI 134  SFPUC Switchgear and Cabling Additional Work.  Addition of LED Skirt Lighting, Increased Foot Candela and Other Emergency Backup Elements
7.2 10.4 10.4 10.4 10.4 14.1B	COR 310599 COR 311646 COR 311155-1 COR 311397 CR T-517 COR 311034 COR 311970 COR 312021	\$450,000 \$650,000 \$370,000 \$1,200,000 \$2,100,000 \$2,500,000 \$450,000 \$450,000	8/24/2018 11/10/2017 11/10/2017 4/5/2018 2/16/2018 11/10/2017 8/31/2017 8/31/2017 2/16/2018	11/17/2017 11/17/2017 3/21/2018 2/16/2018 11/17/2017 11/17/2017 8/31/2017 2/16/2018	\$370,000 \$1,200,000 \$2,100,000 \$2,500,000 \$1,100,000 \$280,000 \$450,000		Scope Procurement	TJPA CMGC CMGC TJPA CMGC TJPA CMGC TJPA TJPA/Reimbursable TJPA TJPA TJPA TJPA TJPA TJPA	CFD	120V Power to Crown Corr Doors  Deck Steel Plates at Tall Curbs  Roof Built Up Slab  ASI 143 - Incorporation of Phase 1.5 Converge Network Package  A1 Light Fixtures  TG10.4 Revised ERRCS Scope From ASI 134  SFPUC Switchgear and Cabling Additional Work.  Addition of LED Skirt Lighting, Increased Foot Candela and Other Emergency Backup Elements  CR T-319 ASI 148 Incorporation of RFI Responses
7.2 10.4 10.4 10.4 10.4 14.1B 16.0	COR 310599 COR 311646 COR 311155-1 COR 311397 CR T-517 COR 311034 COR 311970 COR 312021 CCC 0324	\$450,000 \$650,000 \$370,000 \$1,200,000 \$2,100,000 \$2,500,000 \$450,000 \$450,000	8/24/2018 11/10/2017 11/10/2017 4/5/2018 2/16/2018 11/10/2017 8/31/2017 8/31/2017 2/16/2018	11/17/2017 11/17/2017 3/21/2018 2/16/2018 11/17/2017 11/17/2017 2/16/2018	\$370,000 \$1,200,000 \$2,100,000 \$2,500,000 \$1,100,000 \$280,000 \$450,000	\$428,811	Scope Procurement Owner Requested	TJPA CMGC CMGC TJPA CMGC TJPA CMGC TJPA TJPA/Reimbursable TJPA TJPA TJPA TJPA TJPA	CFD	120V Power to Crown Corr Doors  Deck Steel Plates at Tall Curbs  Roof Built Up Slab  ASI 143 - Incorporation of Phase 1.5 Converge Network Package  A1 Light Fixtures  TG10.4 Revised ERRCS Scope From ASI 134  SFPUC Switchgear and Cabling Additional Work.  Addition of LED Skirt Lighting, Increased Foot Candela and Other Emergency Backup Elements  CR T-319 ASI 148 Incorporation of RFI Responses  Gantry Beams at Ground Level above Transformer Vaults per ASI 121
7.2 10.4 10.4 10.4 10.4 14.1B 16.0	COR 310599 COR 311646 COR 311155-1 COR 311397 CR T-517 COR 311034 COR 311970 COR 312021	\$450,000 \$650,000 \$370,000 \$1,200,000 \$2,100,000 \$2,500,000 \$450,000 \$450,000	8/24/2018 11/10/2017 11/10/2017 4/5/2018 2/16/2018 11/10/2017 8/31/2017 8/31/2017 2/16/2018	11/17/2017 11/17/2017 3/21/2018 2/16/2018 11/17/2017 11/17/2017 2/16/2018	\$370,000 \$1,200,000 \$2,100,000 \$2,500,000 \$1,100,000 \$280,000 \$450,000	\$428,811 \$708,975	Scope Procurement	TJPA CMGC CMGC TJPA CMGC TJPA CMGC TJPA TJPA/Reimbursable TJPA TJPA TJPA TJPA TJPA TJPA	CFD	120V Power to Crown Corr Doors  Deck Steel Plates at Tall Curbs  Roof Built Up Slab  ASI 143 - Incorporation of Phase 1.5 Converge Network Package  A1 Light Fixtures  TG10.4 Revised ERRCS Scope From ASI 134  SFPUC Switchgear and Cabling Additional Work.  Addition of LED Skirt Lighting, Increased Foot Candela and Other Emergency Backup Elements  CR T-319 ASI 148 Incorporation of RFI Responses
7.2 10.4 10.4 10.4 10.4 14.1B 16.0	COR 310599 COR 311646 COR 311155-1 COR 311397 CR T-517 COR 311034 COR 311970 COR 312021 CCC 0324	\$450,000 \$650,000 \$370,000 \$1,200,000 \$2,100,000 \$2,500,000 \$450,000 \$450,000	8/24/2018 11/10/2017 11/10/2017 4/5/2018 2/16/2018 11/10/2017 8/31/2017 8/31/2017 2/16/2018	11/17/2017 11/17/2017 3/21/2018 2/16/2018 11/17/2017 11/17/2017 2/16/2018	\$370,000 \$1,200,000 \$2,100,000 \$2,500,000 \$1,100,000 \$280,000 \$450,000		Scope Procurement Owner Requested	TJPA CMGC CMGC TJPA CMGC TJPA CMGC TJPA TJPA/Reimbursable TJPA TJPA TJPA TJPA TJPA	CFD	120V Power to Crown Corr Doors  Deck Steel Plates at Tall Curbs  Roof Built Up Slab  ASI 143 - Incorporation of Phase 1.5 Converge Network Package  A1 Light Fixtures  TG10.4 Revised ERRCS Scope From ASI 134  SFPUC Switchgear and Cabling Additional Work.  Addition of LED Skirt Lighting, Increased Foot Candela and Other Emergency Backup Elements  CR T-319 ASI 148 Incorporation of RFI Responses  Gantry Beams at Ground Level above Transformer Vaults per ASI 121
7.2 10.4 10.4 10.4 10.4 14.1B 16.0	COR 310599 COR 311646 COR 311155-1 COR 311397 CR T-517 COR 311034 COR 311970 COR 312021 CCC 0324	\$450,000 \$650,000 \$370,000 \$1,200,000 \$2,100,000 \$2,500,000 \$450,000 \$450,000	8/24/2018 11/10/2017 11/10/2017 4/5/2018 2/16/2018 11/10/2017 8/31/2017 8/31/2017 2/16/2018	11/17/2017 11/17/2017 3/21/2018 2/16/2018 11/17/2017 11/17/2017 2/16/2018 2/17/2017 11/18/2016	\$370,000 \$1,200,000 \$2,100,000 \$2,500,000 \$1,100,000 \$280,000 \$450,000		Scope Procurement Owner Requested	TJPA CMGC CMGC TJPA CMGC TJPA CMGC TJPA TJPA/Reimbursable TJPA TJPA TJPA TJPA TJPA	CFD	120V Power to Crown Corr Doors  Deck Steel Plates at Tall Curbs  Roof Built Up Slab  ASI 143 - Incorporation of Phase 1.5 Converge Network Package  A1 Light Fixtures  TG10.4 Revised ERRCS Scope From ASI 134  SFPUC Switchgear and Cabling Additional Work.  Addition of LED Skirt Lighting, Increased Foot Candela and Other Emergency Backup Elements  CR T-319 ASI 148 Incorporation of RFI Responses  Gantry Beams at Ground Level above Transformer Vaults per ASI 121  Additional Wall Plates at Lower Concourse Walls
7.2 10.4 10.4 10.4 10.4 14.1B 16.0	COR 310599 COR 311646 COR 311155-1 COR 311397 CR T-517 COR 311034 COR 311970 COR 312021  CCO 0324 CCO 0312	\$450,000 \$650,000 \$370,000 \$1,200,000 \$2,100,000 \$2,500,000 \$450,000 \$450,000 \$455,000	8/24/2018 11/10/2017 11/10/2017 4/5/2018 2/16/2018 11/10/2017 8/31/2017 2/16/2018 2/6/2017 11/7/2016	11/17/2017 11/17/2017 3/21/2018 2/16/2018 11/17/2017 11/17/2017 2/16/2018 2/17/2017 11/18/2016	\$370,000 \$1,200,000 \$2,100,000 \$2,500,000 \$1,100,000 \$280,000 \$450,000 \$455,000 \$750,000	\$708,975	Scope Procurement Owner Requested Owner Requested	TJPA CMGC CMGC TIPA CMGC TJPA CMGC TJPA TJPA/Reimbursable TJPA TJPA TJPA TJPA TJPA TJPA TJPA TJPA	CFD	120V Power to Crown Corr Doors  Deck Steel Plates at Tall Curbs  Roof Built Up Slab  ASI 143 - Incorporation of Phase 1.5 Converge Network Package  A1 Light Fixtures  TG10.4 Revised ERRCS Scope From ASI 134  SFPUC Switchgear and Cabling Additional Work.  Addition of LED Skirt Lighting, Increased Foot Candela and Other Emergency Backup Elements  CR T-319 ASI 148 Incorporation of RFI Responses  Gantry Beams at Ground Level above Transformer Vaults per ASI 121  Additional Wall Plates at Lower Concourse Walls  Added plate to short curbs to support deformed bars per RFI T-3184 and added plates for tall curbs between GL
7.2 10.4 10.4 10.4 10.4 14.1B 16.0	COR 310599 COR 311646 COR 311155-1 COR 311397 CR T-517 COR 311034 COR 311970 COR 312021  CCO 0324 CCO 0312	\$450,000 \$650,000 \$370,000 \$1,200,000 \$2,100,000 \$2,500,000 \$450,000 \$450,000 \$455,000	8/24/2018 11/10/2017 11/10/2017 4/5/2018 2/16/2018 11/10/2017 8/31/2017 2/16/2018 2/6/2017 11/7/2016	11/17/2017 11/17/2017 3/21/2018 2/16/2018 11/17/2017 11/17/2017 8/31/2017 2/16/2018 2/17/2017 11/18/2016	\$370,000 \$1,200,000 \$2,100,000 \$2,500,000 \$1,100,000 \$280,000 \$450,000 \$450,000 \$750,000	\$708,975	Scope Procurement Owner Requested Owner Requested	TJPA CMGC CMGC TIPA CMGC TJPA CMGC TJPA TJPA/Reimbursable TJPA TJPA TJPA TJPA TJPA TJPA TJPA TJPA	CFD	120V Power to Crown Corr Doors  Deck Steel Plates at Tall Curbs  Roof Built Up Slab  ASI 143 - Incorporation of Phase 1.5 Converge Network Package  A1 Light Fixtures  TG10.4 Revised ERRCS Scope From ASI 134  SFPUC Switchgear and Cabling Additional Work.  Addition of LED Skirt Lighting, Increased Foot Candela and Other Emergency Backup Elements  CR T-319 ASI 148 Incorporation of RFI Responses  Gantry Beams at Ground Level above Transformer Vaults per ASI 121  Additional Wall Plates at Lower Concourse Walls  Added plate to short curbs to support deformed bars per RFI T-3184 and added plates for tall curbs between GL
7.2 10.4 10.4 10.4 10.4 14.1B 16.0 7.2 7.2 7.2	COR 310599 COR 311646 COR 311155-1 COR 311397 CR T-517 COR 311034 COR 311970 COR 312021  CCO 0324 CCO 0312  CCO 0269.1	\$450,000 \$650,000 \$370,000 \$1,200,000 \$2,100,000 \$1,300,000 \$450,000 \$450,000 \$450,000 \$750,000	8/24/2018 11/10/2017 11/10/2017 4/5/2018 2/16/2018 11/10/2017 8/31/2017 2/16/2018 2/6/2017 11/7/2016	11/17/2017 11/17/2017 3/21/2018 2/16/2018 11/17/2017 11/17/2017 8/31/2017 2/16/2018 2/17/2017 11/18/2016	\$370,000 \$1,200,000 \$2,100,000 \$2,500,000 \$1,100,000 \$280,000 \$450,000 \$450,000 \$750,000	\$708,975 \$254,308	Scope Procurement Owner Requested Owner Requested Owner Requested	TJPA CMGC CMGC TJPA CMGC TJPA CMGC TJPA TJPA/Reimbursable TJPA TJPA TJPA  TJPA TJPA TJPA TJPA TJP	CFD	120V Power to Crown Corr Doors Deck Steel Plates at Tall Curbs Roof Built Up Slab ASI 143 - Incorporation of Phase 1.5 Converge Network Package A1 Light Fixtures TG10.4 Revised ERRCS Scope From ASI 134 SFPUC Switchgear and Cabling Additional Work. Addition of LED Skirt Lighting, Increased Foot Candela and Other Emergency Backup Elements CR T-319 ASI 148 Incorporation of RFI Responses  Gantry Beams at Ground Level above Transformer Vaults per ASI 121 Additional Wall Plates at Lower Concourse Walls Added plate to short curbs to support deformed bars per RFI T-3184 and added plates for tall curbs between GL 10-20
7.2 10.4 10.4 10.4 10.4 14.1B 16.0	COR 310599 COR 311646 COR 311155-1 COR 311397 CR T-517 COR 311034 COR 311970 COR 312021  CCO 0324 CCO 0312  CCO 0269.1	\$450,000 \$650,000 \$370,000 \$1,200,000 \$2,100,000 \$1,300,000 \$450,000 \$450,000 \$450,000 \$750,000	8/24/2018 11/10/2017 11/10/2017 4/5/2018 2/16/2018 11/10/2017 8/31/2017 2/16/2018 2/6/2017 11/7/2016	11/17/2017 11/17/2017 3/21/2018 2/16/2018 11/17/2017 11/17/2017 8/31/2017 2/16/2018 2/17/2017 11/18/2016 8/24/2016	\$370,000 \$1,200,000 \$2,100,000 \$2,500,000 \$1,100,000 \$280,000 \$450,000 \$450,000 \$750,000	\$708,975 \$254,308	Scope Procurement Owner Requested Owner Requested Owner Requested	TJPA CMGC CMGC TJPA CMGC TJPA CMGC TJPA TJPA/Reimbursable TJPA TJPA TJPA  TJPA TJPA TJPA TJPA TJP	CFD	120V Power to Crown Corr Doors  Deck Steel Plates at Tall Curbs  Roof Built Up Slab  ASI 143 - Incorporation of Phase 1.5 Converge Network Package  A1 Light Fixtures  TG10.4 Revised ERRCS Scope From ASI 134  SFPUC Switchgear and Cabling Additional Work.  Addition of LED Skirt Lighting, Increased Foot Candela and Other Emergency Backup Elements  CR T-319 ASI 148 Incorporation of RFI Responses  Gantry Beams at Ground Level above Transformer Vaults per ASI 121  Additional Wall Plates at Lower Concourse Walls  Added plate to short curbs to support deformed bars per RFI T-3184 and added plates for tall curbs between GL 10-20  Install additional rebar, formwork and concrete for Partition walls at Lower Concourse per ASI 128.
7.2 10.4 10.4 10.4 10.4 14.1B 16.0 7.2 7.2 7.2	COR 310599 COR 311646 COR 311155-1 COR 311397 CR T-517 COR 311034 COR 311970 COR 312021  CCO 0324 CCO 0312  CCO 0269.1  CCO 0291	\$450,000 \$650,000 \$370,000 \$1,200,000 \$2,100,000 \$1,100,000 \$450,000 \$450,000 \$750,000 \$325,000	8/24/2018 11/10/2017 11/10/2017 4/5/2018 2/16/2018 11/10/2017 8/31/2017 2/16/2018 2/6/2017 11/7/2016 8/22/2016 11/7/2016	11/17/2017 11/17/2017 3/21/2018 2/16/2018 11/17/2017 11/17/2017 2/16/2018 2/17/2017 11/18/2016 8/24/2016 8/24/2016	\$370,000 \$1,200,000 \$2,100,000 \$2,500,000 \$1,100,000 \$280,000 \$450,000 \$750,000 \$325,000 \$368,000 \$260,000	\$708,975 \$254,308 \$317,592	Scope Procurement Owner Requested Owner Requested Owner Requested Owner Requested	TJPA CMGC CMGC TIPA CMGC TJPA CMGC TJPA TJPA TJPA TJPA TJPA TJPA TJPA TJPA	CFD	120V Power to Crown Corr Doors  Deck Steel Plates at Tall Curbs  Roof Built Up Slab  ASI 143 - Incorporation of Phase 1.5 Converge Network Package  A1 Light Fixtures  TG10.4 Revised ERRCS Scope From ASI 134  SFPUC Switchgear and Cabling Additional Work.  Addition of LED Skirt Lighting, Increased Foot Candela and Other Emergency Backup Elements  CR T-319 ASI 148 Incorporation of RFI Responses  Gantry Beams at Ground Level above Transformer Vaults per ASI 121  Additional Wall Plates at Lower Concourse Walls  Added plate to short curbs to support deformed bars per RFI T-3184 and added plates for tall curbs between GL 10-20  Install additional rebar, formwork and concrete for Partition walls at Lower Concourse per ASI 128.  Changes to the GL 35 Seismic Joints due to the OCS footing interrupting the joints and replacing the SJ cover with 1" steel plate  Added seismic joint at Salesforce Tower Pedestrian Bridge per ASI 137
7.2 10.4 10.4 10.4 10.4 14.1B 16.0 7.2 7.2 7.2 7.2	COR 310599 COR 311646 COR 311155-1 COR 311397 CR T-517 COR 311034 COR 311970 COR 312021  CCO 0324 CCO 0312  CCO 0269.1  CCO 0291  COR 311367 CCO 0316 CCO 0304	\$450,000 \$650,000 \$1,200,000 \$2,100,000 \$2,500,000 \$450,000 \$450,000 \$450,000 \$325,000 \$325,000 \$368,000 \$260,000 \$694,000 \$118,000	8/24/2018 11/10/2017 11/10/2017 4/5/2018 2/16/2018 11/10/2017 8/31/2017 2/16/2018 2/6/2017 11/7/2016 8/22/2016 11/7/2016	11/17/2017 11/17/2017 3/21/2018 2/16/2018 11/17/2017 11/17/2017 2/16/2018 2/17/2017 11/18/2016 8/24/2016 8/24/2016	\$370,000 \$1,200,000 \$2,100,000 \$2,500,000 \$1,100,000 \$280,000 \$450,000 \$455,000 \$750,000 \$368,000 \$260,000 \$694,000 \$118,000	\$708,975 \$254,308 \$317,592 -\$101,621	Scope Procurement Owner Requested Owner Requested Owner Requested Owner Requested	TJPA CMGC CMGC TJPA CMGC TJPA CMGC TJPA TJPA TJPA TJPA TJPA TJPA TJPA TJPA	CFD	120V Power to Crown Corr Doors  Deck Steel Plates at Tall Curbs  Roof Built Up Slab  ASI 143 - Incorporation of Phase 1.5 Converge Network Package  A1 Light Fixtures  TG10.4 Revised ERRCS Scope From ASI 134  SFPUC Switchgear and Cabling Additional Work.  Addition of LED Skirt Lighting, Increased Foot Candela and Other Emergency Backup Elements  CR T-319 ASI 148 Incorporation of RFI Responses  Gantry Beams at Ground Level above Transformer Vaults per ASI 121  Additional Wall Plates at Lower Concourse Walls  Added plate to short curbs to support deformed bars per RFI T-3184 and added plates for tall curbs between GL 10-20  Install additional rebar, formwork and concrete for Partition walls at Lower Concourse per ASI 128.  Changes to the GL 35 Seismic Joints due to the OCS footing interrupting the joints and replacing the SJ cover with 1" steel plate  Added seismic joint at Salesforce Tower Pedestrian Bridge per ASI 137  Roof Park scope, Heat Pump Changes, & Duct Reroute per ASI 128
7.2 10.4 10.4 10.4 10.4 14.1B 16.0 7.2 7.2 7.2 7.2 7.6	COR 310599 COR 311646 COR 311155-1 COR 311397 CR T-517 COR 311034 COR 311970 COR 312021  CCO 0324 CCO 0312  CCO 0269.1 CCO 0291  COR 311367 CCO 0316	\$450,000 \$650,000 \$1,200,000 \$2,100,000 \$2,500,000 \$450,000 \$450,000 \$450,000 \$325,000 \$368,000 \$260,000	8/24/2018 11/10/2017 11/10/2017 4/5/2018 2/16/2018 11/10/2017 8/31/2017 2/16/2018 2/6/2017 11/7/2016 8/22/2016 11/7/2016 8/22/2016	11/17/2017 11/17/2017 3/21/2018 2/16/2018 11/17/2017 8/31/2017 2/16/2018 2/17/2017 11/18/2016 8/24/2016 8/24/2016	\$370,000 \$1,200,000 \$2,100,000 \$2,500,000 \$1,100,000 \$280,000 \$450,000 \$455,000 \$750,000 \$368,000 \$260,000 \$694,000 \$118,000	\$708,975 \$254,308 \$317,592 -\$101,621 \$546,055	Scope Procurement Owner Requested Owner Requested Owner Requested Owner Requested Owner Requested Owner Requested	TJPA CMGC CMGC TIPA CMGC TJPA CMGC TJPA TJPA TJPA TJPA TJPA TJPA TJPA TJPA	CFD	120V Power to Crown Corr Doors  Deck Steel Plates at Tall Curbs  Roof Built Up Slab  ASI 143 - Incorporation of Phase 1.5 Converge Network Package  A1 Light Fixtures  TG10.4 Revised ERRCS Scope From ASI 134  SFPUC Switchgear and Cabling Additional Work.  Addition of LED Skirt Lighting, Increased Foot Candela and Other Emergency Backup Elements  CR T-319 ASI 148 Incorporation of RFI Responses  Gantry Beams at Ground Level above Transformer Vaults per ASI 121  Additional Wall Plates at Lower Concourse Walls  Added plate to short curbs to support deformed bars per RFI T-3184 and added plates for tall curbs between GL 10-20  Install additional rebar, formwork and concrete for Partition walls at Lower Concourse per ASI 128.  Changes to the GL 35 Seismic Joints due to the OCS footing interrupting the joints and replacing the SJ cover with 1" steel plate  Added seismic joint at Salesforce Tower Pedestrian Bridge per ASI 137
7.2 10.4 10.4 10.4 11.4 14.1B 16.0 7.2 7.2 7.2 7.2 7.6 10.3 13.1	COR 310599 COR 311646 COR 311155-1 COR 311397 CR T-517 COR 311034 COR 311970 COR 312021  CCO 0324 CCO 0312  CCO 0269.1  CCO 0291  COR 311367 CCO 0316 CCO 0304	\$450,000 \$650,000 \$1,200,000 \$2,100,000 \$2,500,000 \$450,000 \$450,000 \$450,000 \$325,000 \$325,000 \$368,000 \$260,000 \$694,000 \$118,000	8/24/2018 11/10/2017 11/10/2017 4/5/2018 2/16/2018 11/10/2017 8/31/2017 2/16/2018 2/6/2016 8/22/2016 8/22/2016 8/22/2016 8/22/2016	11/17/2017 11/17/2017 3/21/2018 2/16/2018 11/17/2017 11/17/2017 2/16/2018 2/17/2017 11/18/2016 8/24/2016 11/18/2016 8/24/2016 8/24/2016	\$370,000 \$1,200,000 \$2,100,000 \$2,500,000 \$1,100,000 \$280,000 \$450,000 \$455,000 \$750,000 \$368,000 \$260,000 \$694,000 \$118,000	\$708,975 \$254,308 \$317,592 -\$101,621 \$546,055 \$117,841	Scope Procurement Owner Requested	TJPA CMGC CMGC TJPA CMGC TJPA CMGC TJPA TJPA TJPA TJPA TJPA TJPA TJPA TJPA	CFD	120V Power to Crown Corr Doors  Deck Steel Plates at Tall Curbs  Roof Built Up Slab  ASI 143 - Incorporation of Phase 1.5 Converge Network Package  A1 Light Fixtures  TG10.4 Revised ERRCS Scope From ASI 134  SFPUC Switchgear and Cabling Additional Work.  Addition of LED Skirt Lighting, Increased Foot Candela and Other Emergency Backup Elements  CR T-319 ASI 148 Incorporation of RFI Responses  Gantry Beams at Ground Level above Transformer Vaults per ASI 121  Additional Wall Plates at Lower Concourse Walls  Added plate to short curbs to support deformed bars per RFI T-3184 and added plates for tall curbs between GL 10-20  Install additional rebar, formwork and concrete for Partition walls at Lower Concourse per ASI 128.  Changes to the GL 35 Seismic Joints due to the OCS footing interrupting the joints and replacing the SJ cover with 1" steel plate  Added seismic joint at Salesforce Tower Pedestrian Bridge per ASI 137  Roof Park scope, Heat Pump Changes, & Duct Reroute per ASI 128
7.2 10.4 10.4 10.4 10.4 14.1B 16.0 7.2 7.2 7.2 7.2 7.6 7.6	COR 310599 COR 311646 COR 311155-1 COR 311397 CR T-517 COR 311034 COR 311970 COR 312021  CCO 0324 CCO 0312  CCO 0269.1  CCO 0291  COR 311367 CCO 0316 CCO 0304	\$450,000 \$650,000 \$1,200,000 \$2,100,000 \$2,500,000 \$450,000 \$450,000 \$450,000 \$325,000 \$325,000 \$368,000 \$260,000 \$694,000 \$118,000	8/24/2018 11/10/2017 11/10/2017 4/5/2018 2/16/2018 11/10/2017 8/31/2017 2/16/2018 2/6/2016 8/22/2016 8/22/2016 8/22/2016 8/22/2016 2/6/2017 2/6/2017	11/17/2017 11/17/2017 3/21/2018 2/16/2018 11/17/2017 11/17/2017 2/16/2018 2/17/2017 11/18/2016 8/24/2016 11/18/2016 8/24/2016 8/24/2016	\$370,000 \$1,200,000 \$2,100,000 \$2,500,000 \$1,100,000 \$280,000 \$450,000 \$455,000 \$750,000 \$368,000 \$368,000 \$694,000 \$118,000 \$420,000	\$708,975 \$254,308 \$317,592 -\$101,621 \$546,055 \$117,841	Scope Procurement Owner Requested	TJPA CMGC CMGC TJPA CMGC TJPA CMGC TJPA TJPA TJPA TJPA TJPA TJPA TJPA TJPA	CFD	120V Power to Crown Corr Doors  Deck Steel Plates at Tall Curbs  Roof Built Up Slab  ASI 143 - Incorporation of Phase 1.5 Converge Network Package  A1 Light Fixtures  TG10.4 Revised ERRCS Scope From ASI 134  SFPUC Switchgear and Cabling Additional Work.  Addition of LED Skirt Lighting, Increased Foot Candela and Other Emergency Backup Elements  CR T-319 ASI 148 Incorporation of RFI Responses  Gantry Beams at Ground Level above Transformer Vaults per ASI 121  Additional Wall Plates at Lower Concourse Walls  Added plate to short curbs to support deformed bars per RFI T-3184 and added plates for tall curbs between GL 10-20  Install additional rebar, formwork and concrete for Partition walls at Lower Concourse per ASI 128.  Changes to the GL 35 Seismic Joints due to the OCS footing interrupting the joints and replacing the SJ cover with 1" steel plate  Added seismic joint at Salesforce Tower Pedestrian Bridge per ASI 137  Roof Park scope, Heat Pump Changes, & Duct Reroute per ASI 128  Landscape Changes per ASI 138
7.2 10.4 10.4 10.4 11.4 14.1B 16.0 7.2 7.2 7.2 7.2 7.6 10.3 13.1	COR 310599 COR 311646 COR 311155-1 COR 311397 CR T-517 COR 311034 COR 311970 COR 312021  CCO 0324 CCO 0312  CCO 0269.1  CCO 0291  COR 311367 CCO 0316 CCO 0304 CCO 0366	\$450,000 \$650,000 \$1,200,000 \$2,100,000 \$2,500,000 \$450,000 \$450,000 \$450,000 \$325,000 \$368,000 \$260,000 \$694,000 \$118,000	8/24/2018 11/10/2017 11/10/2017 4/5/2018 2/16/2018 11/10/2017 8/31/2017 2/16/2018 2/6/2017 11/7/2016 8/22/2016 8/22/2016 11/7/2016 8/22/2016 2/6/2017 2/6/2017 2/6/2017	11/17/2017 11/17/2017 3/21/2018 2/16/2018 11/17/2017 8/31/2017 2/16/2018 2/17/2017 11/18/2016 8/24/2016 8/24/2016 8/24/2016 2/17/2017 2/17/2017	\$370,000 \$1,200,000 \$2,100,000 \$2,500,000 \$1,100,000 \$280,000 \$450,000 \$455,000 \$750,000 \$325,000 \$368,000 \$260,000 \$694,000 \$118,000 \$420,000	\$708,975 \$254,308 \$317,592 -\$101,621 \$546,055 \$117,841 \$7,185	Scope Procurement Owner Requested Owner Requested Owner Requested Owner Requested Owner Requested Owner Requested From Requested Owner Requested	TJPA CMGC CMGC TJPA CMGC TJPA CMGC TJPA TJPA TJPA TJPA TJPA TJPA TJPA TJPA	CFD	120V Power to Crown Corr Doors  Deck Steel Plates at Tall Curbs  Roof Built Up Slab  ASI 143 - Incorporation of Phase 1.5 Converge Network Package  A1 Light Fixtures  TG10.4 Revised ERRCS Scope From ASI 134  SFPUC Switchgear and Cabling Additional Work.  Addition of LED Skirt Lighting, Increased Foot Candela and Other Emergency Backup Elements  CR T-319 ASI 148 Incorporation of RFI Responses  Gantry Beams at Ground Level above Transformer Vaults per ASI 121  Additional Wall Plates at Lower Concourse Walls  Added plate to short curbs to support deformed bars per RFI T-3184 and added plates for tall curbs between GL 10-20  Install additional rebar, formwork and concrete for Partition walls at Lower Concourse per ASI 128.  Changes to the GL 35 Seismic Joints due to the OCS footing interrupting the joints and replacing the SJ cover with 1" steel plate  Added seismic joint at Salesforce Tower Pedestrian Bridge per ASI 137  Roof Park scope, Heat Pump Changes, & Duct Reroute per ASI 128  Landscape Changes per ASI 138
7.2 10.4 10.4 10.4 10.4 14.1B 16.0 7.2 7.2 7.2 7.2 7.6 7.6 10.3 13.1	COR 310599 COR 311646 COR 311155-1 COR 311397 CR T-517 COR 311034 COR 311970 COR 312021  CCO 0324 CCO 0312  CCO 0269.1  CCO 0291  COR 311367 CCO 0316 CCO 0304 CCO 0366  COR 311408	\$450,000 \$650,000 \$1,200,000 \$2,100,000 \$2,500,000 \$450,000 \$450,000 \$450,000 \$325,000 \$325,000 \$325,000 \$3450,000 \$325,000 \$325,000 \$3325,000 \$3330,000 \$430,000	8/24/2018 11/10/2017 11/10/2017 4/5/2018 2/16/2018 11/10/2017 8/31/2017 2/16/2018 2/6/2017 11/7/2016 8/22/2016 8/22/2016 11/7/2016 8/22/2016 2/6/2017 2/6/2017 2/6/2017 5/8/2017 8/31/2017	11/17/2017 11/17/2017 3/21/2018 2/16/2018 11/17/2017 11/17/2017 2/16/2018 2/17/2017 11/18/2016 8/24/2016 8/24/2016 11/18/2016 8/24/2016 2/17/2017 2/17/2017	\$370,000 \$1,200,000 \$2,100,000 \$2,500,000 \$1,100,000 \$280,000 \$450,000 \$455,000 \$750,000 \$368,000 \$368,000 \$118,000 \$420,000 \$3,300,000 \$900,000	\$708,975 \$254,308 \$317,592 -\$101,621 \$546,055 \$117,841 \$7,185 \$2,045,732	Scope Procurement Owner Requested	TJPA CMGC CMGC TJPA CMGC TJPA CMGC TJPA TJPA TJPA TJPA TJPA TJPA TJPA TJPA	CFD	120V Power to Crown Corr Doors Deck Steel Plates at Tall Curbs Roof Built Up Slab ASI 143 - Incorporation of Phase 1.5 Converge Network Package A1 Light Fixtures TG10.4 Revised ERRCS Scope From ASI 134 SFPUC Switchgear and Cabling Additional Work. Addition of LED Skirt Lighting, Increased Foot Candela and Other Emergency Backup Elements CR T-319 ASI 148 Incorporation of RFI Responses  Gantry Beams at Ground Level above Transformer Vaults per ASI 121 Additional Wall Plates at Lower Concourse Walls Added plate to short curbs to support deformed bars per RFI T-3184 and added plates for tall curbs between GL 10-20 Install additional rebar, formwork and concrete for Partition walls at Lower Concourse per ASI 128. Changes to the GL 35 Seismic Joints due to the OCS footing interrupting the joints and replacing the SJ cover with 1" steel plate Added seismic joint at Salesforce Tower Pedestrian Bridge per ASI 137 Roof Park scope, Heat Pump Changes, & Duct Reroute per ASI 128 Landscape Changes per ASI 138  W-Systems Impact to Structural Concrete Package. COR submitted at \$6.3M, but \$3M due to inefficiencies /delays
7.2 10.4 10.4 10.4 10.4 14.1B 16.0 7.2 7.2 7.2 7.2 7.6 10.3 13.1 7.2	COR 310599 COR 311646 COR 311155-1 COR 311397 CR T-517 COR 311034 COR 311970 COR 312021  CCO 0324 CCO 0312  CCO 0269.1  CCO 0291  COR 311367 CCO 0316 CCO 0304 CCO 0366  COR 311408 COR 311981	\$450,000 \$650,000 \$370,000 \$1,200,000 \$2,100,000 \$2,500,000 \$450,000 \$450,000 \$325,000 \$325,000 \$368,000 \$118,000 \$410,000 \$420,000	8/24/2018 11/10/2017 11/10/2017 4/5/2018 2/16/2018 11/10/2017 8/31/2017 2/16/2018 2/6/2017 11/7/2016 8/22/2016 8/22/2016 11/7/2016 8/22/2016 2/6/2017 2/6/2017 5/8/2017	11/17/2017 11/17/2017 3/21/2018 2/16/2018 11/17/2017 11/17/2017 2/16/2018 2/16/2018 2/17/2017 11/18/2016 8/24/2016 11/18/2016 8/24/2016 2/17/2017 2/17/2017 5/19/2017 8/31/2017	\$370,000 \$1,200,000 \$2,100,000 \$2,500,000 \$1,100,000 \$280,000 \$450,000 \$750,000 \$368,000 \$368,000 \$118,000 \$420,000 \$3,300,000 \$900,000 \$1,000,000	\$708,975 \$254,308 \$317,592 -\$101,621 \$546,055 \$117,841 \$7,185 \$2,045,732 \$783,827	Scope Procurement Owner Requested Owner Requested Owner Requested Owner Requested Owner Requested Owner Requested From Requested Owner Requested	TJPA CMGC CMGC TIPA CMGC TJPA CMGC TJPA TJPA TJPA TJPA TJPA TJPA TJPA TJPA	CFD	120V Power to Crown Corr Doors  Deck Steel Plates at Tall Curbs  Roof Built Up Slab  ASI 143 - Incorporation of Phase 1.5 Converge Network Package  A1 Light Fixtures  TG10.4 Revised ERRCS Scope From ASI 134  SFPUC Switchgear and Cabling Additional Work.  Addition of LED Skirt Lighting, Increased Foot Candela and Other Emergency Backup Elements  CR T-319 ASI 148 Incorporation of RFI Responses  Gantry Beams at Ground Level above Transformer Vaults per ASI 121  Additional Wall Plates at Lower Concourse Walls  Added plate to short curbs to support deformed bars per RFI T-3184 and added plates for tall curbs between GL 10-20  Install additional rebar, formwork and concrete for Partition walls at Lower Concourse per ASI 128.  Changes to the GL 35 Seismic Joints due to the OCS footing interrupting the joints and replacing the SJ cover with 1" steel plate  Added seismic joint at Salesforce Tower Pedestrian Bridge per ASI 137  Roof Park scope, Heat Pump Changes, & Duct Reroute per ASI 128  Landscape Changes per ASI 138  W-Systems Impact to Structural Concrete Package. COR submitted at \$6.3M, but \$3M due to inefficiencies /delays Rebar Changes from Bid Including ASI 128
7.2 10.4 10.4 10.4 11.4 14.1B 16.0 7.2 7.2 7.2 7.2 7.6 10.3 13.1 7.2 7.2	COR 310599 COR 311646 COR 311155-1 COR 311397 CR T-517 COR 311034 COR 311970 COR 312021  CCO 0324 CCO 0312  CCO 0269.1  CCO 0291  COR 311367 CCO 0316 CCO 0304 CCO 0366  COR 311408 COR 311981 CCO 0426	\$450,000 \$650,000 \$370,000 \$1,200,000 \$2,100,000 \$1,100,000 \$450,000 \$450,000 \$325,000 \$325,000 \$368,000 \$118,000 \$420,000 \$33,300,000 \$900,000 \$1,000,000	8/24/2018 11/10/2017 11/10/2017 4/5/2018 2/16/2018 11/10/2017 8/31/2017 2/16/2018 2/6/2017 11/7/2016 8/22/2016 8/22/2016 2/6/2017 2/6/2017 5/8/2017 8/31/2017 8/31/2017 8/31/2017 5/8/2017 5/8/2017	11/17/2017 11/17/2017 3/21/2018 2/16/2018 11/17/2017 8/31/2017 2/16/2018 2/17/2017 11/18/2016 8/24/2016 8/24/2016 8/24/2016 2/17/2017 2/17/2017 5/19/2017 8/31/2017 8/31/2017 5/19/2017	\$370,000 \$1,200,000 \$2,100,000 \$2,500,000 \$1,100,000 \$280,000 \$450,000 \$750,000 \$325,000 \$368,000 \$368,000 \$118,000 \$420,000 \$3,300,000 \$900,000 \$97,000 \$912,000	\$708,975 \$254,308 \$317,592 -\$101,621 \$546,055 \$117,841 \$7,185 \$2,045,732 \$783,827 \$443,801	Scope Procurement Owner Requested From Requested Owner Requested From Requested Errors & Omissions	TJPA CMGC CMGC TJPA CMGC TJPA CMGC TJPA TJPA TJPA TJPA TJPA TJPA TJPA TJPA	CFD	Deck Steel Plates at Tall Curbs  Roof Built Up Slab  ASI 143 - Incorporation of Phase 1.5 Converge Network Package  A1 Light Fixtures  TG10.4 Revised ERRCS Scope From ASI 134  SFPUC Switchgear and Cabling Additional Work.  Addition of LED Skirt Lighting, Increased Foot Candela and Other Emergency Backup Elements  CR T-319 ASI 148 Incorporation of RFI Responses  Gantry Beams at Ground Level above Transformer Vaults per ASI 121  Additional Wall Plates at Lower Concourse Walls  Added plate to short curbs to support deformed bars per RFI T-3184 and added plates for tall curbs between GL 10-20  Install additional rebar, formwork and concrete for Partition walls at Lower Concourse per ASI 128.  Changes to the GL 35 Seismic Joints due to the OCS footing interrupting the joints and replacing the SJ cover with 1" steel plate  Added seismic joint at Salesforce Tower Pedestrian Bridge per ASI 137  Roof Park scope, Heat Pump Changes, & Duct Reroute per ASI 128  Landscape Changes per ASI 138  W-Systems Impact to Structural Concrete Package. COR submitted at \$6.3M, but \$3M due to inefficiencies /delays Rebar Changes from Bid Including ASI 128  Built Up Slabs in Ground Level and Roof Level
7.2 10.4 10.4 10.4 11.4 14.1B 16.0 7.2 7.2 7.2 7.2 7.6 7.6 10.3 13.1 7.2 7.2 7.2	COR 310599 COR 311646 COR 311155-1 COR 311397 CR T-517 COR 311034 COR 311970 COR 312021  CCO 0324 CCO 0324 CCO 0312  CCO 0269.1 CCO 0291  COR 311367 CCO 0316 CCO 0304 CCO 0366  COR 311408 COR 311981 CCO 0426 CCO 0412 CCO 0416 CCO 0416 CCO 0416	\$450,000 \$650,000 \$370,000 \$1,200,000 \$2,100,000 \$1,100,000 \$450,000 \$450,000 \$750,000 \$325,000 \$325,000 \$3450,000 \$3450,000 \$3450,000 \$3450,000 \$3450,000 \$3450,000 \$3450,000 \$3450,000 \$3450,000 \$3450,000 \$3450,000 \$3450,000 \$3450,000 \$3450,000 \$3450,000 \$3450,000 \$3450,000 \$3450,000 \$3450,000	8/24/2018 11/10/2017 11/10/2017 4/5/2018 2/16/2018 11/10/2017 8/31/2017 2/16/2018 2/6/2017 11/7/2016 8/22/2016 11/7/2016 8/22/2016 2/6/2017 2/6/2017 5/8/2017 8/31/2017 5/8/2017	11/17/2017 11/17/2017 3/21/2018 2/16/2018 11/17/2017 8/31/2017 2/16/2018 2/17/2017 11/18/2016 8/24/2016 8/24/2016 8/24/2016 2/17/2017 2/17/2017 5/19/2017 8/31/2017 5/19/2017 5/19/2017	\$370,000 \$1,200,000 \$2,100,000 \$2,500,000 \$1,100,000 \$280,000 \$450,000 \$750,000 \$325,000 \$368,000 \$368,000 \$118,000 \$420,000 \$3,300,000 \$900,000 \$97,000 \$912,000	\$708,975 \$254,308 \$317,592 -\$101,621 \$546,055 \$117,841 \$7,185 \$2,045,732 \$783,827 \$443,801 \$76,576	Scope Procurement Owner Requested From Scope Procurement Owner Requested Errors & Omissions	TJPA CMGC CMGC TIPA CMGC TJPA CMGC TJPA TJPA TJPA TJPA TJPA TJPA TJPA TJPA	CFD	Deck Steel Plates at Tall Curbs Roof Built Up Slab ASI 143 - Incorporation of Phase 1.5 Converge Network Package A1 Light Fixtures TG10.4 Revised ERRCS Scope From ASI 134 SFPUC Switchgear and Cabling Additional Work. Addition of LED Skirt Lighting, Increased Foot Candela and Other Emergency Backup Elements CR T-319 ASI 148 Incorporation of RFI Responses  Gantry Beams at Ground Level above Transformer Vaults per ASI 121 Additional Wall Plates at Lower Concourse Walls Added plate to short curbs to support deformed bars per RFI T-3184 and added plates for tall curbs between GL 10-20  Install additional rebar, formwork and concrete for Partition walls at Lower Concourse per ASI 128. Changes to the GL 35 Seismic Joints due to the OCS footing interrupting the joints and replacing the SJ cover with 1" steel plate Added seismic joint at Salesforce Tower Pedestrian Bridge per ASI 137 Roof Park scope, Heat Pump Changes, & Duct Reroute per ASI 128 Landscape Changes per ASI 138  W-Systems Impact to Structural Concrete Package. COR submitted at \$6.3M, but \$3M due to inefficiencies /delays Rebar Changes from Bid Including ASI 128 Built Up Slabs in Ground Level and Roof Level Roof Park Restaurant Cable Guardrail Continuity Plate per RFI T-5041 Series
7.2 10.4 10.4 10.4 11.4 11.4 16.0 7.2 7.2 7.2 7.2 7.6 7.6 10.3 13.1 7.2 7.2 7.2 7.3 8.11R 8.11R	COR 310599 COR 311646 COR 311155-1 COR 311397 CR T-517 COR 311034 COR 311970 COR 312021  CCO 0324 CCO 0324 CCO 0325  CCO 0269.1  CCO 0291  COR 311367 CCO 0316 CCO 0304 CCO 0366  COR 311408 COR 311981 CCO 0426 CCO 0412 CCO 0416 CCO 0416 CCO 1063 311044	\$450,000 \$650,000 \$1,200,000 \$2,100,000 \$2,500,000 \$450,000 \$450,000 \$450,000 \$325,000 \$325,000 \$368,000 \$368,000 \$118,000 \$450,000 \$118,000 \$118,000 \$118,000 \$118,000 \$260,000 \$3,300,000 \$1,000,000 \$270,000 \$270,000 \$3300,000	8/24/2018 11/10/2017 11/10/2017 4/5/2018 2/16/2018 11/10/2017 8/31/2017 2/16/2018 2/6/2017 11/7/2016 8/22/2016 8/22/2016 2/6/2017 2/6/2017 5/8/2017 8/31/2017 8/31/2017 8/31/2017 8/31/2017 5/8/2017 5/8/2017	11/17/2017 11/17/2017 3/21/2018 2/16/2018 11/17/2017 8/31/2017 2/16/2018  2/17/2017 11/18/2016 8/24/2016 8/24/2016 8/24/2016 2/17/2017 2/17/2017 5/19/2017 8/31/2017 2/17/2017 5/19/2017 5/19/2017 5/19/2017 5/19/2017 5/19/2017	\$370,000 \$1,200,000 \$2,100,000 \$2,500,000 \$1,100,000 \$280,000 \$450,000 \$455,000 \$750,000 \$368,000 \$368,000 \$694,000 \$118,000 \$420,000 \$1,000,000 \$900,000 \$97,000 \$97,000 \$912,000 \$3300,000	\$708,975 \$254,308 \$317,592 -\$101,621 \$546,055 \$117,841 \$7,185 \$2,045,732 \$783,827 \$443,801 \$76,576 \$859,088 \$254,915 \$290,121	Scope Procurement Owner Requested From Scope Procurement Owner Requested From Scomissions Errors Scomissions	TJPA CMGC CMGC TIPA CMGC TJPA CMGC TJPA TJPA TJPA TJPA TJPA TJPA TJPA TJPA	CFD	Deck Steel Plates at Tall Curbs Roof Built Up Slab ASI 143 - Incorporation of Phase 1.5 Converge Network Package A1 Light Fixtures TG10.4 Revised ERRCS Scope From ASI 134 SFPUC Switchgear and Cabling Additional Work. Addition of LED Skirt Lighting, Increased Foot Candela and Other Emergency Backup Elements CR T-319 ASI 148 Incorporation of RFI Responses  Gantry Beams at Ground Level above Transformer Vaults per ASI 121 Additional Wall Plates at Lower Concourse Walls Added plate to short curbs to support deformed bars per RFI T-3184 and added plates for tall curbs between GL 10-20 Install additional rebar, formwork and concrete for Partition walls at Lower Concourse per ASI 128. Changes to the GL 35 Seismic Joints due to the OCS footing interrupting the joints and replacing the SJ cover with 1" steel plate Added seismic joint at Salesforce Tower Pedestrian Bridge per ASI 137 Roof Park scope, Heat Pump Changes, & Duct Reroute per ASI 128 Landscape Changes per ASI 138  W-Systems Impact to Structural Concrete Package. COR submitted at \$6.3M, but \$3M due to inefficiencies /delays Rebar Changes from Bid Including ASI 128 Built Up Slabs in Ground Level and Roof Level Roof Park Restaurant Cable Guardrail Continuity Plate per RFI T-5041 Series W-13 Frame Modifications W-12 Perimeter Expansion Joint Infill Plate ASI 141 Changes for Metal Panel System
7.2 10.4 10.4 10.4 10.4 14.1B 16.0 7.2 7.2 7.2 7.6 7.6 10.3 13.1 7.2 7.2 7.3 8.11R 8.4 10.2	COR 310599 COR 311646 COR 311155-1 COR 311397 CR T-517 COR 311034 COR 311970 COR 312021  CCO 0324 CCO 0312  CCO 0269.1  CCO 0291  COR 311367 CCO 0316 CCO 0304 CCO 0366  COR 311408 COR 311981 CCO 0426 CCO 0416 CCO 0416 CCO 0416 CCO 1063 311044 *COR 311542	\$450,000 \$650,000 \$1,200,000 \$2,100,000 \$2,500,000 \$450,000 \$450,000 \$450,000 \$325,000 \$325,000 \$325,000 \$325,000 \$3450,000 \$325,000 \$3450,000 \$325,000 \$325,000 \$325,000 \$325,000 \$325,000 \$325,000 \$325,000 \$325,000 \$3300,000 \$3300,000 \$310,000 \$310,000 \$310,000	8/24/2018 11/10/2017 11/10/2017 4/5/2018 2/16/2018 11/10/2017 8/31/2017 2/16/2018 2/6/2017 11/7/2016 8/22/2016 8/22/2016 2/6/2017 2/6/2017 5/8/2017 8/31/2017 5/8/2017 5/8/2017 5/8/2017 11/10/2017	11/17/2017 11/17/2017 3/21/2018 2/16/2018 11/17/2017 8/31/2017 2/16/2018 2/16/2018 2/17/2017 11/18/2016 8/24/2016 8/24/2016 8/24/2016 2/17/2017 2/17/2017 5/19/2017 8/31/2017 2/17/2017 5/19/2017 5/19/2017 5/19/2017 11/17/2017	\$370,000 \$1,200,000 \$2,100,000 \$2,500,000 \$1,100,000 \$280,000 \$450,000 \$455,000 \$750,000 \$368,000 \$368,000 \$694,000 \$118,000 \$420,000 \$1,000,000 \$97,000 \$97,000 \$270,000 \$300,000 \$1,010,000 \$300,000 \$1,010,000	\$708,975 \$254,308 \$317,592 -\$101,621 \$546,055 \$117,841 \$7,185 \$2,045,732 \$783,827 \$443,801 \$76,576 \$859,088 \$254,915 \$290,121 \$917,040	Scope Procurement Owner Requested Owner Requested Owner Requested Owner Requested Owner Requested Owner Requested From Scope Procurement Owner Requested Owner Requested Owner Requested Owner Requested Owner Requested Owner Requested From Scopies Ownissions Errors Scopies Ownissions	TJPA CMGC CMGC TJPA CMGC TJPA CMGC TJPA TJPA TJPA TJPA TJPA TJPA TJPA TJPA	CFD	Deck Steel Plates at Tall Curbs Roof Built Up Slab ASI 143 - Incorporation of Phase 1.5 Converge Network Package A1 Light Fixtures TG10.4 Revised ERRCS Scope From ASI 134 SFPUC Switchgear and Cabling Additional Work. Addition of LED Skirt Lighting, Increased Foot Candela and Other Emergency Backup Elements CR T-319 ASI 148 Incorporation of RFI Responses  Gantry Beams at Ground Level above Transformer Vaults per ASI 121 Additional Wall Plates at Lower Concourse Walls Added plate to short curbs to support deformed bars per RFI T-3184 and added plates for tall curbs between GL 10-20 Install additional rebar, formwork and concrete for Partition walls at Lower Concourse per ASI 128. Changes to the GL 35 Seismic Joints due to the OCS footing interrupting the joints and replacing the SJ cover with 1" steel plate Added seismic joint at Salesforce Tower Pedestrian Bridge per ASI 137 Roof Park scope, Heat Pump Changes, & Duct Reroute per ASI 128 Landscape Changes per ASI 138  W-Systems Impact to Structural Concrete Package. COR submitted at \$6.3M, but \$3M due to inefficiencies /delays Rebar Changes from Bid Including ASI 128 Built Up Slabs in Ground Level and Roof Level Roof Park Restaurant Cable Guardrail Continuity Plate per RFI T-5041 Series W-13 Frame Modifications W-12 Perimeter Expansion Joint Infill Plate ASI 141 Changes for Metal Panel System Gray Water System Clarification RFIs
7.2 10.4 10.4 10.4 11.4 11.4 16.0 7.2 7.2 7.2 7.2 7.6 7.6 10.3 13.1 7.2 7.2 7.2 7.3 8.11R 8.11R	COR 310599 COR 311646 COR 311155-1 COR 311397 CR T-517 COR 311034 COR 311970 COR 312021  CCO 0324 CCO 0324 CCO 0325  CCO 0269.1  CCO 0291  COR 311367 CCO 0316 CCO 0304 CCO 0366  COR 311408 COR 311981 CCO 0426 CCO 0412 CCO 0416 CCO 0416 CCO 1063 311044	\$450,000 \$650,000 \$1,200,000 \$2,100,000 \$2,500,000 \$450,000 \$450,000 \$450,000 \$325,000 \$325,000 \$368,000 \$368,000 \$118,000 \$450,000 \$118,000 \$118,000 \$118,000 \$118,000 \$260,000 \$3,300,000 \$1,000,000 \$270,000 \$270,000 \$3300,000	8/24/2018 11/10/2017 11/10/2017 4/5/2018 2/16/2018 11/10/2017 8/31/2017 8/31/2017 2/16/2018  2/6/2017 11/7/2016 8/22/2016 8/22/2016 2/6/2017 2/6/2017 2/6/2017 5/8/2017 5/8/2017 5/8/2017 5/8/2017 5/8/2017 5/8/2017	11/17/2017 11/17/2017 3/21/2018 2/16/2018 11/17/2017 11/17/2017 8/31/2017 2/16/2018  2/17/2017 11/18/2016 8/24/2016 8/24/2016 8/24/2016 2/17/2017 2/17/2017 5/19/2017 8/31/2017 8/31/2017 5/19/2017 5/19/2017 11/17/2017	\$370,000 \$1,200,000 \$2,100,000 \$2,500,000 \$1,100,000 \$280,000 \$450,000 \$455,000 \$750,000 \$325,000 \$368,000 \$368,000 \$420,000 \$118,000 \$420,000 \$900,000 \$91,000,000 \$97,000 \$97,000 \$1,000,000 \$3300,000 \$1,000,000 \$300,000 \$300,000 \$300,000 \$300,000 \$300,000	\$708,975 \$254,308 \$317,592 -\$101,621 \$546,055 \$117,841 \$7,185 \$2,045,732 \$783,827 \$443,801 \$76,576 \$859,088 \$254,915 \$290,121	Scope Procurement Owner Requested From Scope Procurement Owner Requested From Scomissions Errors Scomissions	TJPA CMGC CMGC TIPA CMGC TJPA CMGC TJPA TJPA TJPA TJPA TJPA TJPA TJPA TJPA	CFD	Deck Steel Plates at Tall Curbs Roof Built Up Slab ASI 143 - Incorporation of Phase 1.5 Converge Network Package A1 Light Fixtures TG10.4 Revised ERRCS Scope From ASI 134 SFPUC Switchgear and Cabling Additional Work. Addition of LED Skirt Lighting, Increased Foot Candela and Other Emergency Backup Elements CR T-319 ASI 148 Incorporation of RFI Responses  Gantry Beams at Ground Level above Transformer Vaults per ASI 121 Additional Wall Plates at Lower Concourse Walls Added plate to short curbs to support deformed bars per RFI T-3184 and added plates for tall curbs between GL 10-20 Install additional rebar, formwork and concrete for Partition walls at Lower Concourse per ASI 128. Changes to the GL 35 Seismic Joints due to the OCS footing interrupting the joints and replacing the SJ cover with 1" steel plate Added seismic joint at Salesforce Tower Pedestrian Bridge per ASI 137 Roof Park scope, Heat Pump Changes, & Duct Reroute per ASI 128 Landscape Changes per ASI 138  W-Systems Impact to Structural Concrete Package. COR submitted at \$6.3M, but \$3M due to inefficiencies /delays Rebar Changes from Bid Including ASI 128 Built Up Slabs in Ground Level and Roof Level Roof Park Restaurant Cable Guardrail Continuity Plate per RFI T-5041 Series W-13 Frame Modifications W-12 Perimeter Expansion Joint Infill Plate ASI 141 Changes for Metal Panel System

## Agenda Item #8 - Construction Amendments and Changes Log (Transit Center)

8/17/2018

8/:	17/2018									
Trade Package	CCO/CR No.	Total Value	Date submitted to CRC	Date No Exceptions Taken by CRC	Amount No Exceptions Taken by CRC	CCO Final Approved Amount	CCO Category	Contingency Source	Fund Source	CCO Issue
10.2	CCO 0343	\$800,000	2/6/2017	3/22/2017	\$800,000	\$673,785	Errors & Omissions	TJPA	TIFIA	Connection to Sewer Mains per RFI T-5029
10.4	COR 311110	\$325,000	8/31/2017	8/31/2017	\$350,000	\$323,964	Errors & Omissions	TJPA	CFD	TG10.4 ASI 141 Electrical Changes
13.1	COR 311561	\$350,000	8/31/2017	8/31/2017	\$350,000	\$134,590	Errors & Omissions	TJPA	CFD	Shoe Design Changes at Bus Fountain
13.2	CCO 0362	\$300,000	5/8/2017	5/19/2017	\$300,000	\$297,101	Errors & Omissions	TJPA	City Financing	Add FC 4 Layers and revision to INS-14 per ASI 138
18.1	COR 312068	\$300,000	11/10/2017	11/17/2017	\$300,000	\$233,583	Errors & Omissions	TJPA	TIFIA	Changes to Cal Trans Substation Building Lot Elevations
18.1	COR 311099	\$1,500,000	11/10/2017	11/17/2017	\$1,500,000	\$367,498	Errors & Omissions	TJPA	City Financing	Hinge 9 Expansion Joint
18.1	CCO 0290.1	\$736,000	8/22/2016	8/24/2016	\$736,000	\$691,702	Errors & Omissions	TJPA	Bridge Loan	Revisions to the Bus Ramp Cable Stay Hinge 8 Expansion Joint per ASI 150-015.
18.1	CCO 0373.1	\$475,000	8/22/2016	8/24/2016	\$475,000	\$367,498	Errors & Omissions	TJPA	TIFIA	Revisions to the Bus Ramp Cable Stay Hinge 9 Expansion Joint per ASI 150-016.
5.10	COR 312195.1	\$280,000	2/16/2017	2/16/2017	\$280,000	\$259,546	Schedule Mitigation	CMGC	CFD	Grand Hall Temporary Floor Protection
7.2	CCO 1059	\$1,200,000	2/6/2017	2/17/2017	\$1,200,000	\$895,298	Schedule Mitigation	CMGC	TIFIA	Schedule Recovery for TG 7.2 scope, premium time only, using CM/GC Contingency per contract.
7.1	CCO 1043	\$425,000	2/6/2017	2/17/2017	\$425,000	\$425,742	Skanska Settlement	CMGC	TIFIA	Seismic Upgrades to Access Trestle. ** Final amount \$742 over NTE of \$425,000.
7.1	COR 310296.1	\$672,750	8/22/2016	8/24/2016	\$672,750	\$637,974	BBII Settlement	TJPA	CFD	Removal of Sand Inclusions in Bus Deck level cast node pads, CCO 428 added
n/a	CCO 0410	\$42,000	8/31/2017	8/31/2017	\$42,000	\$41,689	Scope Procurement	TJPA	City Financing	Roof Park Restaurant Handrail IPE Wood Cap
	COR	\$43,600	11/10/2017	11/17/2017	\$43,600	\$43,600	Scope Procurement	TJPA	CFD	Tim Hawkinson Concrete Removal Contract
4.2	*CR T-383.A	\$5,500,000	4/5/2018	4/5/2018	\$5,500,000	\$1,563,188	Scope Procurement	TJPA	CFD	Traction Power (Base Scope up to 2nd Street). \$5.5 million was presented to the CRC on 2/16/18.
4.2	CR T-383.A	\$4,500,000	4/5/2018	-	n/a		Scope Procurement	TJPA	n/a	Traction Power (2nd Street to 5th Street) - Scope Voided
4.2	COR 311395	\$550,000	11/10/2017	11/17/2017		\$258,750	Scope Procurement	TJPA	CFD	OCS Fiberglass Support System Installation
5.XX	*CCO 1129, 1132	\$4,500,000	2/16/2018	2/16/2018		\$4,500,000	Scope Procurement	CMGC	CFD	Additional Temporary Facilities for Phased Completion (Post December 22, 2017)
5.10	*CCO1137	\$3,350,000	4/5/2018	3/21/2018		\$3,350,000	Scope Procurement	CMGC	CFD	Additional Temporary Facilities for Phased Completion, for June through August 2018
5.10	COR 310496	\$1,400,000	11/10/2017	11/17/2017	\$1,400,000	\$1,398,300	Scope Procurement	TJPA	CFD	Overhead Protection at First and Fremont
5.10	COR 310505.1	\$1,108,000	11/10/2017	11/17/2017	\$1,108,000	\$1,052,716	Scope Procurement	TJPA	CFD	Site Dewatering
5.10	COR 310841.1	\$2,170,000	11/10/2017	11/17/2017	\$2,170,000	\$1,780,013	Scope Procurement	TJPA	CFD	Furnish Site Dumpsters for LEED Related Construction Waste
5.10	COR 312079	\$500,000	11/10/2017	11/17/2017	\$500,000	\$477,112	Scope Procurement	TJPA	CFD	Provide Plywood Backer Boards for IDF/MDF Rooms
7.2	CCO 0393.1	\$250,000	2/6/2017	2/17/2017	\$250,000	\$87,153	Scope Procurement	TJPA	MTC AB1171	Drum Café Revisions
7.2	CCO 0328	\$445,000	11/7/2016	11/18/2016		\$434,946	Scope Procurement	TJPA	City Financing	West Throat Vent Shaft Concrete
7.3	CCO 0370	\$60,000	5/8/2017	5/19/2017	\$60,000	\$56,579	Scope Procurement	TJPA	City Financing	Bent Plate Embed and SS Base Plate from ASI 128 for Roof Park Restaurant
7.6	CCO 1035	\$330,000	8/22/2016	8/24/2016		\$307,144	Scope Procurement	CMGC	Land Sales	Installation of Mat Slab walls at water storage tank previously not procured.
8.4	*COR 310812	\$450,000	2/16/2018	2/16/2018		\$416,919	Scope Procurement	CMGC	CFD	W-1 and W16C Installation Buy-out Design Impacts
8.6R	CCO 0344	\$480,000	5/8/2017	5/19/2017	\$480,000	\$476,903	Scope Procurement	TJPA	TIFIA	ASI 140 Drop-in Span Aluminum Enclosure, VE Item.
8.6R	CCO 0309	\$250,000	2/6/2017	2/17/2017	\$250,000	\$249,554	Scope Procurement	TJPA	City Financing	Procurement of the W2 and W3 head of wall assembly
8.11R	CCO 0378	\$480,000	8/31/2017	8/31/2017	\$480,000	\$475,387	Scope Procurement	TJPA	TIFIA	Procurement of Glazing Door Hardware Package previously not procured. **Estimate increased
10.2	CCO 0186	\$1,486,000	8/22/2016	8/24/2016	\$1,486,000	\$1,232,298	Scope Procurement	TJPA	Prop K	Revisions and additions to plumbing system per ASI 128.
10.4	COR 312695	\$595,000	4/5/2018	3/21/2018		\$593,007	Scope Procurement	TJPA	CFD	E2 Pylon Louvers and Frosted Lens
10.4	COR 311671.1	\$600,000	8/31/2017	8/31/2017	\$600,000	\$463,487	Scope Procurement	TJPA	CFD	E2 Pylon Beacon Power per RFI T-4988
10.4	CCO 0284	\$1,330,000	11/7/2016	11/18/2016		\$1,202,996	Scope Procurement	TJPA	TIFIA	Phase 1.5 ASI 144
10.4	CCO 0293.1	\$1,100,000	8/22/2016	8/24/2016	\$1,100,000	\$861,630	Scope Procurement	TJPA	TIFIA	Procurement of the pathway that supports the Emergency Response System per ASI 134.
10.4	CCO 0379	\$390,000	3/22/2017	3/22/2017		\$275,056	Scope Procurement	TJPA	TIFIA	Added Stairwell Lighting per RFI T-5585.1
12.1	COR	\$1,500,000	2/16/2018	2/16/2018		\$1,320,803	Scope Procurement	TJPA	CFD	Traffic Signal Revisions and Streetlight Revisions (Ref CR T-502, T-571, and T-543)
13.1	COR 311740	\$300,000	8/31/2017	8/31/2017		\$97,298	Scope Procurement	TJPA	City Financing	Contract Grow Monthly Maintenance and Storage
13.2	CCO 0277	\$435,000	8/22/2016	8/24/2016		\$401,828	Scope Procurement	TJPA	Land Sales	Procurement and installation of the W2 Roof Trellis and Outriggers per ASI 128 and 138
16.8	CCO 0287	\$261,000	8/22/2016	8/24/2016	\$261,000	\$252,310	Scope Procurement	TJPA	Land Sales	Installation of the Rooftop Restaurant Fireproofing per ASI 128
		, ,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,		. , ,	, , , , , ,	, , , ,				
	Total	\$109,772,350		CCO F	inal Approved Total	\$37,822,243		•		•
		,	. ,			, ,,-				

<sup>\*</sup> Executed since last CRC meeting

\*\* Increased Total Value from Previously Approved

MODS and amounts paid directly by WOJV (not thru TJPA) are not included in this estimate

New Construction Changes
In Process (Presented to CRC)
Approved

Trade Packages:						
4.2	Utility Relocation - Mission St. AWSS					
7.1	Structural Steel					
7.2	Structural Concrete					
7.3	Miscellaneous Metal					
7.6	Topping Slabs, Bus Crash Rail and Expansion Joints					
8.6R	Metal Ceilings					
8.11R	Glass Curtain Wall/Skylights					
10.2	Plumbing					
10.3	Mechanical/HVAC					
10.4	Electrical					
10.5	Fire Protection and Suppression					
13.1	Landscaping and Irrigation					
13.2	Roofing/Waterproofing					
14.1B	Escalators					
16.8	Fireproofing/Intumescent Spray					
18.1	Bus Ramp					

## Agenda Item #8 - Construction Amendments and Changes Log (Bus Storage Facility)

8/21/2018										
Trade Package	CCO/CR No.	Total Value	Date submitted to CRC	Date No Exceptions Taken by CRC	Amount No Exceptions Taken by CRC	CCO Final Approved Amount	CCO Category	Contingency Source	Fund Source	CCO Issue
BSF	CCO # 1	\$9,679	11/6/2017	11/17/2017	\$9,679	\$9,679	Change Condition	TJPA	City Financing	
BSF	CCO # 2	\$889,683	11/8/2017		\$889,683	\$889,683	Change Condition	ТЈРА	City Financing	Class I & Class II Offhaul/Disposal - Additional Qty. the original \$628k value submitted to the CRC at last meeting was an estimate and this new amount of \$889,683.05 k is the final resolution of the quantities.
BSF	CCO # 3	\$1,036	11/6/2017	11/17/2017	\$1,036	\$1,036	Change Condition	TJPA	City Financing	Buried Light Pole Foundation
BSF	CCO # 4	\$6,199	11/6/2017	11/17/2017	\$6,199	\$6,199	Change Condition	TJPA	City Financing	Water Main Potholing for Re-design (T&M)
BSF	CCO # 5	\$21,131	11/6/2017	11/17/2017	\$21,131	\$21,131	Change Condition	TJPA	City Financing	SS Line Relocation Bents 13-14 (LS)
BSF	CCO # 6	\$13,906	11/6/2017		\$13,906	\$13,906	Owner Requested	TJPA	City Financing	Food Court Cleanup (T&M)
BSF	CCO # 7	\$7,905	11/6/2017		\$7,905	\$7,905	Change Condition	TJPA	City Financing	Abut A6 Unsuitable Matl R&R (T&M)
BSF	CCO # 8	\$20,250	11/6/2017	11/17/2017	\$20,250	\$20,250	Change Condition	TJPA	City Financing	Waterline Tie-In Location Change (LS)
BSF BSF	CCO # 9 CCO #10	\$1,251 \$20,000		11/17/2017 11/17/2017	\$1,251 \$20,000	\$1,251 \$19,998	Owner Requested	TJPA TJPA	City Financing	Fence & Graffiti Repairs (T&M) Soundwall CIDH Pile Drilling Conditions
BSF	CCO #10	\$33,699	11/6/2017	11/17/2017	\$33,699	\$19,996	Owner Requested Owner Requested	TJPA	City Financing City Financing	2nd Street OCS Removal & Replacement by SFMTA
BSF	CCO # 12	\$24,315		11/17/2017	\$24,315	\$24,315	Change Condition	TJPA	City Financing	SW1 Footing Conflict
BSF	CCO # 13	\$3,131			\$3,131	\$3,131		TJPA		SW3&4 Utility Conflicts
BSF	CCO # 14	\$99,194	11/6/2017	11/17/2017	\$99,194	+=,===	Change Condition	TJPA	City Financing	AW2 Buried Concrete Conflict
BSF	CCO # 15	\$221,914	11/6/2017	11/17/2017	\$221,914	\$221,914	Change Condition	TJPA	City Financing	Class I Offhaul/Dispose Unit Price Adjustment
BSF	CCO # 16	\$43,925	11/6/2017	11/17/2017	\$43,925	\$43,925	Change Condition	TJPA	City Financing	Class II Offhaul/Dispose Unit Price Adjustment
BSF	CCO # 17	\$10,000.00	11/6/2017	11/17/2017	\$10,000.00	\$8,796.31	Owner Requested	TJPA	City Financing	Bus Link Striping and Signage
BSF	CCO # 18	\$18,722		11/17/2017	\$18,722	\$18,722	Owner Requested	TJPA	City Financing	SW3, SW4, Stillman/3rd Drainage Changes
BSF	CCO # 19	\$4,820		11/17/2017	\$4,820	4,819	Change Condition	TJPA	City Financing	Additional AC Removal BLR 11+50
BSF	CCO #20	\$30,000	11/6/2017	11/17/2017	\$30,000	¢20.070	Owner Requested	TJPA	City Financing	Bus Ramp Supplemental Striping
BSF	CCO #21		12/05/1017	1/15/2017	\$41,109	\$29,079	Owner Requested	ТЈРА	City Financing	Additioal Cost Due to Changes of Sound Wall Height
BSF	CCO #22		12/05/1017	1/15/2017	\$7,742		Owner Requested	TJPA	City Financing	MSE Wall Drainage Changes
BSF	CCO #23	\$917	12/05/1017	1/15/2017	\$917	\$917	Owner Requested	TJPA	City Financing	Spare 2in Conduit for Future EV Charging Station
BSF	CCO #25	\$50,000	12/05/1017	1/15/2017	\$50,000		Owner Requested	TJPA	City Financing	Budgetary Costs for Lighting Inverter
BSF	CCO #26	\$10,433		1/15/2017	\$10,433		Owner Requested	TJPA	City Financing	Additional costs assoicated with Submittal #089-Fire Marshal Comments to add 2 additional card readers.
BSF	CCO #27	\$1,123		1/15/2017	\$1,123	\$1,123		TJPA	City Financing	Per owners request, added three (3) additional 20 MPH signs to the bus link ramp.
BSF	CCO #28	\$4,750	4/5/2018	4/5/2018	\$4,750		Owner Requested	TJPA	City Financing	MCM Premium Time for Falsework Removal
							·			Flashing Beacon, Barrier and striping work for Bus Ramps Project. Previously reported as CCOs 18 and 19
BSF	CCO #29	\$254,691	3/12/2018	3/12/2018	\$330,000	\$254,691	Owner Requested	TJPA	City Financing	for \$330k.
BSF	CCO #30	\$5,000	4/5/2018	4/5/2018	\$5,000	\$4,010	Owner Requested	TJPA	City Financing	Bridge Profilograph Testing
BSF	CCO #31	\$33,335	4/5/2018	4/5/2018	\$33,335	\$33,335	Change Condition	TJPA	City Financing	SW #3 & #4 Drainage Changes
BSF	CCO #32	\$10,771	4/5/2018	4/5/2018	\$10,771	\$10,771	Change Condition	TJPA	City Financing	Bents 11 and 12 drainage Changes
BSF	CCO #33	\$5,000	4/5/2018	4/5/2018	\$5,000		Change Condition	TJPA	City Financing	Costs to move MCM Trailer and Containers
BSF	CCO #34	\$28,178	4/5/2018	4/5/2018	\$28,178	\$28,178	Change Condition	TJPA	City Financing	Remove and Replace Curb at Sta. 14+51 to 15+33
BSF	CCO #35	\$5,000	4/5/2018	4/5/2018	\$5,000		Change Condition	TJPA	City Financing	Restake MSE#3 and RW#1&3
BSF	CCO #36	\$37,000	4/5/2018	4/5/2018	\$37,000		Owner Requested	TJPA	City Financing	Modular Building Material Changes
BSF	CCO #37	\$10,235	4/5/2018	4/5/2018	\$10,235		Owner Requested	TJPA	City Financing	Admin Lockers
BSF	CCO #38	\$26,000	4/5/2018	4/5/2018	\$26,000		Change Condition	TJPA	City Financing	Rental Parking Spaces at Parking Lot
BSF BSF	CCO #39 CCO #40	\$20,000 \$80,000	4/5/2018 4/5/2018	4/5/2018 4/5/2018	\$20,000 \$80,000	¢72.0F4	Change Condition Change Condition	TJPA TJPA	City Financing	Additional Paving Near Existing Parking Lot Type 60-C Missing Scope (Dees Burke)
BSF	CCO #40	\$40,000	4/5/2018	4/5/2018	\$40,000	\$12,654	Owner Requested	TJPA	City Financing  City Financing	Repair High Mast Feeder
BSF	CCO #41	\$40,000	4/5/2018	4/5/2018	\$30,000		Change Condition	TJPA	City Financing	Changes to Water and Fire Line
BSF	CCO #42	\$26,000		4/5/2018	\$26,000		Change Condition	TJPA	City Financing	Additional Soundsorb Cladding
BSF	CCO #44	\$20,000	4/5/2018	4/5/2018	\$20,787		Owner Requested	TJPA	City Financing	LED Upgrade (PHX SL #1)
BSF	CCO #45	\$17,400	4/5/2018	4/5/2018	\$17,400		Owner Requested	TJPA	City Financing	PG&E Feeder (PHX SL #6)
BSF	CCO #46	\$350,000		5/18/2018	\$350,000	\$33,613	Owner Requested	TJPA	City Financing	Bus Ramp Frame 2 turnaround structure
BSF	CCO # 47	\$50,000	5/4/2018	5/18/2018	\$50,000	, , , , , ,	Owner Requested	TJPA	City Financing	Harrison slip ramp addition Channelizers @ 5' spacing (White/white)
BSF	CCO # 48	\$50,000	5/4/2018	5/18/2018	\$50,000		Owner Requested	TJPA	City Financing	Additional Class 1 offhaul at Modular Admin bldg. (Formerly CCO 49)
BSF	CCO # 49	\$38,000					Owner Requested	TJPA	City Financing	3rd Street Entrance with the City & SFMTA, Requirement
BSF	CCO # 50	\$27,500					Owner Requested	TJPA	City Financing	AC Transit Additional Striping & Signs
BSF	CCO # 51	\$33,000			\$20,000		Owner Requested	TJPA	City Financing	Slide Gate at Harrison Ramp (Formerly CCO 48)
BSF	CCO # 52	\$100,000	8/20/2018				Owner Requested	TJPA	City Financing	ASI 150-024 Street Lighting at Clementina, Tehama and Howard Streets
BSF	CCO # 53	\$110,000	8/20/2018				Owner Requested	TJPA	City Financing	BSF low voltage, fiber between BSF and Transit Center Building. Internet
BSF	CCO # 54	\$17,000					Owner Requested	TJPA	City Financing	Clementina street Glarescreen
BSF	CCO # 55	\$182,175					Owner Requested	TJPA	City Financing	Arup RFI 7746-Structure Backfill, Rough Grading, Paving Co.
BSF	CCO # 56	\$12,000					Owner Requested	TJPA	City Financing	BSF Guardrail Ends.
BSF	COR varies		12/05/1017	1/15/2017			Owner Requested	TJPA	City Financing	Misc. Caltrans Changes, Street Light/Pole Changes, Rolling Gate, ASI 023/024
	Total	\$3,365,905	[ <u> </u>	CCO Final	Approved Total	\$1,347,779				

<sup>\*</sup> Executed Recently

