Update on Construction and temporary closure of the Salesforce Transit Center

February 12, 2019






1. Progress on the Girder Remediation/Repair Effort (Dennis)

2. Progress on confirming the Facility-Wide Validation (Ron)




Isometric View



TICANSBAY JOINT POWERS AUTHORITY

Girder Remediation Detail






This graphic has details specific to Fremont street girders

Actions taken since last Board meeting:

- Fremont and First Street remediation material being machined;
- Initial preparation of Fremont street girders has begun.
- Temporary jacks at First Street replaced with steel column shoring.
- Contractor schedule update indicates repair completion no later than June.



Steel column shoring installed at First street in preparation for the permanent plate installation.





Recent Actions

Sample plate being tested at LPI lab







Next Steps

February 2019 actions:

- Finite Element Analysis (FEA) to be presented to PRP.
- Project Team* continuing their building-wide review for other areas that may need further review and/or inspections.

March 2019 actions:

- Project Team* continues building-wide document and field review.
- Materials arrive onsite.
- Commencement of the Fremont and First street remediation.

Repair/Remediation expected to be completed by June.



*Project team consists of TJPA, TT, CM/GC with associated subcontractors and suppliers/fabricators

Schedule

| | January | | | February | | | | March | | | | April | | | | MAY | | | | |
|--|------------|------|------|----------|-----|-----|------|-------|-----|-----|------|-------|-----|------|------|------|-----|--------|------|------|
| | 1/4 | 1/11 | 1/18 | 1/25 | 2/1 | 2/8 | 2/15 | 2/22 | 3/1 | 3/8 | 3/15 | 3/22 | 4/5 | 4/12 | 4/19 | 4/26 | 5/3 | 5/10 5 | i/17 | 5/24 |
| | | | | | | | | | | | | | | | | | | | | |
| MTC ONGOING PEER REVIEW | | | | | | | | | | | | | | | | | | 0 | NGOI | NG |
| DESIGN FIRST STREET REMEDIATION | | | | | | | | | | | | | | | | | | | | |
| MTC PEER REVIEW FOR REMEDIATION (First Street) | | | | | | | | | | | | | | | | | | | | |
| PERMANENT FIX INSTALLATION | \diamond | | | | | | | | | | | | | | | | | | | K |
| Procurement & Installation | Ť | | | | | | | | | | | | | | | | | | e | 5/01 |
| SHORING REMOVAL???? | | | | | | | | | | | | | | | | | | | | |
| REINSTALLATION OF SYSTEMS, FINISHES & CEILINGS | | 1/0 | 2 | | | | | | | | | | | | | | | O | NGO | ING |
| PROJECT TEAM BUILDING-WIDE SEARCH | | | | | | | | | | | | | | | | | | O | NGO | ING |
| MTC PEER REVIEW BUILDING-WIDE VERIFICATION | | | | | | | | | | | | | | | | | | O | NGOI | ING |
| PERFORM ANY REQUIRED BUILDING MITIGATION | | | | | | | | | | | | | | | | | | O | NGO | ING |
| | | | | | | | | | | | | | | | | | | | | |



Ongoing Actions

Full Building Structural Health Check

Evaluation Criteria

Focusing on: Plate Thickness, Flame Cut Edges/Corners, Welding, Plate Toughness, High Tensile Stress

Design & Fabrication Details

Review Typical framing bays at Each Level to identify members/connections that warrant further consideration.

Construction Submittals

Identify specific piece marks and review matching mill certificates, piece drawings, Request for Information (RFIs), and fabrication procedures.

QC & QA Documentation

Examine Third Party Inspection Reports, Observation Reports, Test Reports, etc.

> Onsite Visual Examinations & Testing


> > (if necessary)

Corrective Action Plans

(if necessary)

Progression through the successive sieves of the funnel help separate areas which require further research to confirm to be acceptable.





- Reaffirm Structural Integrity of Building
- Revalidate Full Fire & Life Safety Systems completed in May
- Review Tests & Inspection Records completed in March
- Building Management Systems Commissioning completed in April
- Re-Occupancy Readiness Strategy



- Reaffirm Structural Integrity of Building
 - Complete Engineering Findings & Reports
 - Fracture-related Investigations
 - Complete PRP Remediation Recommendations
 - Follow PRP Building Evaluation Criteria
 - Revalidate Full Fire & Life Safety (F&LS) Systems
 - SFFD and Project Team established parameters for Fire & Life Safety Systems Recertification
 - Restoration of Localized Interruptions Created by Girder Work underway with activation of various zones scheduled to occur between February and May



Review Tests and Inspections

- Concrete Placement Inspection Reports Review
 - 34,240 Test Cylinders were taken
 - All reviewed and accepted with exception of one pending paperwork
- Validated all compaction tests for structural concrete
- Review Field Condition Reports (FCR's) and Non-Compliance Reports (NCR's)
- Current FCR/NCR Stats:
 - There were 4,647 NCRs/FCRs written to date
 - No Systemic or new issues identified during records review
 - Continue FCR and NCR Process through remediation efforts



- Building Management Systems Commissioning
 - Commissioning Progress
 - Pre-functional Check-list Status:
 - Vertical Transportation Systems Complete
 - Fire/Life/Safety Complete (pending repair completion)
 - HVAC 75% complete or in process (remaining pending repairs)
 - Hot Water, BMS, Lighting & Electrical not started
 - Functional Performance Testing
 - Implement Testing Plan per Schedule (update)
 - Measure, Monitor & Report on Functional Test
 - Validate Systems Performance
 - Closeout Documentation Status:
 - Submitted Items 317
 - Unsubmitted Items 542
 - Normal Operations
 - Continual Systems Operational Parameters Monitored
 - Real-time Systems Reporting and Alarming of Issues or Failures

Building Management Systems Commissioning

| | January | | | | | ebrua | | | March 3/1 3/8 3/15 3/22 3/29 | | | | | April | | | | |
|--|----------|------|------|------|--------|-------|--------|---------|---------------------------------|-------|----------|-------|--------------------|----------|------|------|------|----------------------------|
| | 1/4 | 1/11 | 1/18 | 1/25 | 2/1 | 2/8 | 2/15 | 2/22 | 3/1 | 3/8 | 3/15 | 3/22 | 3/29 | 4/5 | 4/12 | 4/19 | 4/26 | |
| HVAC Equipment & Controls | | | | | 1 | | | | | | | | | | | | | |
| Air Handing Units | | | | | | | | | | | | | | | | | | |
| Cooling Towers & Variable Frequency Drives (VFD) | | | | | | | | | | | | | | | | | | |
| Computer Room Air Conditioning (CRAC) units | | | | | | | | | | | | | | | | | | |
| Heat Pumps | | | | | | | | | | | | | | | | | | |
| Radiant Flooring | | | | | | | | | | | <u> </u> | | | | | | | |
| Stair Pressuriaztion | | | | | | | | | | | | | | | | | | |
| Exhaust Fans | | | | | | | | | | | | | | | | | | |
| Supply Fans | <u> </u> | | | | | | | | | | | | | | | | | |
| Dampers / Actuation | | | | | | | | | | | | | $\left - \right $ | | | | | |
| Domestic Hot Water System | | | | | | | | | | | | | | | | | | |
| Building Management Control System | | | | | | | | | | | | | | | | | | |
| (BMCS) Mechanical | | | | | | | | | | | | | | | | | | |
| (BMCS)Elecrical | | | | | | | | | | | | | | | | | | Partial |
| Lighting Systems Control | | | | | | | | | | | | | | | | | | Recommissioning Pending |
| Occupancy Sensors | | | | | | | | | | | | | | | | | | |
| Daylight Dimming | | | | | | | | | | | | | | | | | | Structural |
| Switching Systems | | | | | | | | | | | | | | | | | | Repairs |
| Time Schedules | | | | | | | | | | | [| | | | | | | |
| General Electrical Systems | - | | | | | | | | | | | | | | | | | |
| Uninterrupted Power Supplies (UPS) | | | | | | | | | | | | | | | | | | |
| Generators & ATS Systems | | | | | | | | | | | | | | | | | | |
| Transformers | - | | | | | | | | | | - | | | | | | | |
| | <u> </u> | | | | | | | | | | | | | | | | | |
| Electrical Distribution Boards | | | | | | | | | | ļ | | | | | | | | |
| Power & Energy Monitoring | | | | | | | | | | | | | | | | | | |
| Fire Alarm System | | | i | Com | plete | d wit | n Reco | ertifca | ation I | Pend | ling St | ructu | ral Re | pairs | | | | |
| | ┢ | | | | | | | | | | | | | | | | | |
| Fire Suppression System | — | | | Comp | oleteo | d wit | n Rece | ertifca | ition I | Pendi | ling St | ructu | al Re | pairs | | | 1 | |
| Vertical Transportation | | | | | | | | Co | mplet | ted | | | | <u> </u> | | | | |

Re-Occupancy Readiness

Receive Occupancy Clearance by Zones/Floors

SFFD, DBI, TJPA Inspectors, Building Commissioning Agents

Establish Re-Activation Sequence

- Incremental Activation as early as March to May Timeframe
- Complete & Occupy Tenant Improvement Spaces
- TJPA Office Move to 2nd Floor Space Imminent
- Probable Early Bus Plaza Opening
- Independent Salesforce Park Opening Plausible
- Phased Bus Deck Opening Supports Early Activation
- Present Re-Occupancy Schedule March 2019



Thank You



201 Mission Street, Suite 2100 San Francisco, CA 94105 🔸 415.597.4620 🎍 www.tjpa.org